


USB flash drive quality control flow chart



The step by step flow of production process as below;

1. Chips
2. The shell material
3. Chip test one by one (Testing with H2 software for all the USB FLASH DRIVE 2.0 A GRADE)
4. Enclosures printed logo
5. Assembly
6. Bulk product testing
7. Finished product testing one by one (we have a very rigid inspection process, and all goods need 3 times QC inspection.)
- 8.Surface to wipe
9. Bagging
10. Boxes.
11. Packing.
12. Shipment of goods

